



**Checkpoint**  
by MARTINS

# Lug Nut Indicators & Retainers

Our Lug Nut Indicators make it fast and easy to visually spot any movement of the nut at a glance. We have indicators and retainers that can even help prevent loosening in the first place and tell you if a wheel is overheating. You wouldn't want to manually verify every nut, on every wheel, every day, would you?

## The original loose wheel nut indicator

- 48 teeth for greater point to point accuracy
- World's first biodegradable wheel nut indicators
- Overheating indication - Melting temperature:
  - Standard version: 125°C / 257°F
  - High temperature version: 165°C / 329°F
- UV additive to ensure stability and long life – tested to ISO 11507 standard
- Made in Canada & UK
- Checklock retainer is TUV SUD certified

## Put safety into motion

- Easy to install
- Highly visible
- Overheating indication
- Reduce risk of wheel detachment
- Decreased vehicle down time
- Reduced maintenance costs

By placing the Checkpoints in a recognisable pattern such as point to point, any movement of the nut is clearly visible at a glance.






CHECKPOINT



DUSTITE



CHECKLOCK



CHECKLINK



DUSTITE LR



LUGLOCK

## Indicators

Indicate movement and overheating

## Retainers

Helps prevent loosening of nuts



Made in Canada & UK

